# Nov. Meeting 5

Joint

- numbers on paying down funnel hydro
- snow course pilot
- Ring Crate Inspection
- Ring Crate Concrete Repair
- staffing

Delingmency Report

- BLM fire trespass

- Dead Ox Ton r of Project

- Kingman Lateral ton r

- Dead Ox # 3 bids

- Budget, Preliminary

- COVID VAX Mandate



To:

**Board of Directors** 

Meeting Date: 16 Nov. 2021

RE: Leaky feedlot pipeline

## Attachments:

1. OID Vicinity Map

# Background/Summary/Discussion:

Fred Esplin feedlot has an OID concrete line running under a pen. It is believed that the line predates the CAFO. The new owners are going to reconstruct and improve the pens which triggered an inspection by the state. The state is requiring the leaky line be addressed. OID leadership met on-site with the operator and the state inspector. The consensus was that the line is best relocated around the pen to fix the current and avoid future similar issues.

Per analysis by Mark Carpenter the line needs to be 18" to carry the water due to the flat topography and a total of 2580' of new 80# PVC pipe. The price per foot quoted back to the operator was \$75,000 for all pipe. The pipe cost has increased since then.

Jay spoke with Gary Johnston, new owner, and he is willing to pay for pipe through pens but if he were to pay for anymore, he'd need to be reimbursed.

### **Budget Impact:**

OID: 800' of 18" 80# pipe at \$35/ft = \$28,000 Landowner: 1780' 80# pipe at \$35/ft = \$62,300

# **Recommended Motion:**

I move to approve/deny the relocation and replacement of the pipe through the Fred Esplin feedlot by District crews; with the District paying for 800' of pipe and fittings related thereto and the land owner paying for 1780' of the pipe and fittings through the pen.